

1. Incident Name	2. Date Prepared	3. Time Completed	UNIT DEBRIEF LOG ICS 214B – NDOW
M6H1 – Harvey Response	September 3, 2017		
4. Unit Name/Designators	5. Unit Leader		6. Daily Operational Period
Water Infrastructure Group	Name: Westin Massey (TCEQ) Mark McCasland (EPA R6)		DATE TIME
	Position: Water Infrastructure Group Supervisor		From: September 3, 2017 0800 To: September 4, 2017 0800
7. Personnel Roster Assigned			
Name	ICS Position	Affiliation	
Kathleen Campbell	Drinking Water Site Assessment Team	TCEQ	
Maytham Farris	Drinking Water Site Assessment Team	TCEQ	
Faith Cotton	Drinking Water Site Assessment Team	TCEQ	
Miguel Moreno	Drinking Water Site Assessment Team	EPA R6	
Meaghan Bresnahan	Drinking Water Site Assessment Team	EPA R6	
Thuy Chau	Drinking Water Site Assessment Team	TCEQ	
Destiny Geppert	Drinking Water Site Assessment Team	TCEQ	
Chisara Anoruo	Drinking Water Site Assessment Team	TCEQ	
Josephine Garcia	Drinking Water Site Assessment Team	TCEQ	
Dawn Olivio	Drinking Water Site Assessment Team	TCEQ	
8. Operational Period Debrief			
General Remarks / Accomplishments:			
<p>The five 2-person teams completed site assessments at 24 public water systems. The assessment forms and photos will be provided to the contract for data entry into Response Manager once they arrive at the Houston Branch ICP.</p> <p>There were no reports of injury or accidents.</p>			
<p>ADDITIONAL/SUPPORTING DOCUMENTATION: <input checked="" type="checkbox"/>Response Manager <input type="checkbox"/>Photographs <input type="checkbox"/>Video <input type="checkbox"/>Logbook <input type="checkbox"/>Other: _____</p>			
Health & Safety Issues / Problem Areas:			
None			
Next Operational Period Requirements (Additional-Reduction in Resources) (Tactical Changes):			
None			

